

METHOD W SINGLE VALVE

NOTE: FOR WAX VALVES INCLUDING LV/XL SERIES OR ELECTRONIC VALVES INCLUDING NUCLEUS AND PROTON



HIGH TEMPERATURE FIXTURES (IF APPLICABLE)

SEE INSTALLATION INSTRUCTIONS FOR VALVE SPECIFIC PIPING DIAGRAMS AND SET UP PROCEDURE.

FOR MULTIPLE TEMPERED LOOPS A BALANCING VALVE AND CHECK VALVE MUST BE INSTALLED ON EACH LOOP DOWNSTREAM OF TEMPERED FIXTURES.

